


Spacing required for milling collars in one pass

Not shown:
3 off M6 hex nuts retaining the various parts
3mm bore paint pickup tube (plastic)